

ESTIMATE DETAIL



PROJECT NAME

	DESCRIPTION	QTY	UNIT	RATE	TOTAL (\$)
04	Division 04 - Masonry				
1	<u>Structural Masonry</u>				
2	Ext. Wall - CMU Wall (Non Bearing) E8A - 8" x 10.83' H @ P1 Level	465	LF		
3	Ext. Wall - CMU Wall (Non Bearing) E8A - 8" x 10.83' H @ P1 Level	5,038	SF		
4	Int. Wall - CMU Wall @ Stair Core M8A.2 - 8" x 9.25' H	804	LF		
5	Int. Wall - CMU Wall @ Stair Core M8A.2 - 8" x 9.25' H	7,434	SF		
6	Int. Wall - CMU Wall @ Elevator Core M8A.2 - 8" x 9.25' H	271	LF		
7	Int. Wall - CMU Wall @ Elevator Core M8A.2 - 8" x 9.25' H	2,507	SF		
8					
9	<u>Ext. Masonry Finish</u>				
10	3.2 - Cast Stone Veneer - A-201B	1,932	SF		
11	3.2 - Cast Stone Veneer - 10' H - A-101B	28	LF		
12	3.2 - Cast Stone Veneer - 10' H - A-101B	275	SF		
13	Ext. - Brick Veneer @ Side walls (not visible in elevations) - 10' H @ Level 1	127	LF		
14	Ext. - Brick Veneer @ Side walls (not visible in elevations) - 10' H @ Level 1	1,269	SF		
15	Ext. - Brick Veneer @ Side walls (not visible in elevations) - 8.5' H	455	LF		
16	Ext. - Brick Veneer @ Side walls (not visible in elevations) - 8.5' H	3,868	SF		
17	Ext. - Stone Veneer @ Side walls (not visible in elevations) - 11' H @ Level 2 to 6	103	LF		
18	Ext. - Stone Veneer @ Side walls (not visible in elevations) - 11' H @ Level 2 to 6	1,137	SF		
19	Ext. - Brick Veneer @ Side walls (not visible in elevations) - 11' H @ Level 2 to 6	86	LF		
20	Ext. - Brick Veneer @ Side walls (not visible in elevations) - 11' H @ Level 2 to 6	950	SF		
21	Ext. Wall Finish - Brick	13,651	SF		
22	Ext. Wall Finish - Stone Cladding	5,510	SF		
23	Ext. Wall Finish - Finish Type Missing	162	SF		
24	<u>Critical Repairs</u>				
25	No work for Critical Repairs Funding				No Work
26	<u>Additional Program</u>				
27	No work for Critical Repairs Funding				No Work
TOTAL COST					\$