

| Area | Trade Package | Conditions | Item No. | QTY | Unit | Notes |
|---------|---------------|--|----------|-------|------|-------|
| Phase-1 | 09A-Drywall | GWB Ceiling | 23 | 12 | SF | |
| Phase-1 | 09A-Drywall | GWB_Soffit_1'0"Ht | 27 | 10 | SF | |
| Phase-1 | 09A-Drywall | GWB_Soffit_6"Ht | 28 | 9 | SF | |
| Phase-1 | 09A-Drywall | GWB_Soffit_7"Ht | 30 | 2.6 | SF | |
| Phase-1 | 09A-Drywall | GWB_Soffit_1'6"Ht | 31 | 3.6 | SF | |
| Phase-1 | 09A-Drywall | GWB_Soffit_4"Ht | 32 | 13.6 | SF | |
| Phase-1 | 09A-Drywall | Existing Partition Upgraded to Acoustic_OG4 | 222 | 15 | LF | |
| Phase-1 | 09A-Drywall | New Acoustic Partition_OG4 | 223 | 29 | LF | |
| Phase-1 | 09A-Drywall | New Furring wall_OF3_Non Structural Metal Framing | 226 | 16 | LF | |
| Phase-1 | 09A-Drywall | New Partition_OG4 | 230 | 13 | LF | |
| Phase-1 | 09A-Drywall | New Acoustic Partition_OG4_Above Storefront & glass wall | 234 | 12 | LF | |
| Phase-1 | 09A-Drywall | New Furring wall_OF4 | 235 | 198 | LF | |
| Phase-1 | 09A-Drywall | New Acoustic Partition_OG4-B_Ballistic Level Rated | 236 | 27 | LF | |
| Phase-1 | 09A-Drywall | New Furring wall_OG3 | 238 | 31 | LF | |
| Phase-1 | 09A-Drywall | Gypsum Partition_OG4P_Non Rated_Partial Ht Partition_8" Ht | 241 | 32 | LF | |
| Phase-1 | 09A-Drywall | GWB_Soffit_5'0"Ht | 244 | 20 | SF | |
| Phase-1 | 09A-Drywall | New Acoustic Partition_OG4_Above Storefront & glass wall | 268 | 19 | LF | |
| Phase-1 | 09A-Drywall | New Acoustic Partition_OG4_Above Storefront & glass wall | 272 | 33 | LF | |
| Phase-1 | 09A-Drywall | New Partition_Above Storefront & glass wall_OG4 | 273 | 39 | LF | |
| Phase-1 | 09A-Drywall | New Partition_Above Storefront & glass wall_OG4 | 275 | 12 | LF | |
| Phase-1 | 09A-Drywall | New Acoustic Partition_OG4_Above Storefront & glass wall | 276 | 12 | LF | |
| Phase-1 | 09A-Drywall | New Partition_OG4_Glass-Mat Water Resistant @ RR | 406 | 19 | LF | |
| Phase-2 | 09A-Drywall | GWB Ceiling | 23 | 6.35 | SF | |
| Phase-2 | 09A-Drywall | GWB_Soffit_1'6"Ht | 31 | 9.36 | SF | |
| Phase-2 | 09A-Drywall | Existing Partition Upgraded to Acoustic_OG4 | 222 | 12.5 | LF | |
| Phase-2 | 09A-Drywall | New Acoustic Partition_OG4 | 223 | 19.85 | LF | |
| Phase-2 | 09A-Drywall | New Furring wall_OF3_Non Structural Metal Framing | 226 | 20.5 | LF | |
| Phase-2 | 09A-Drywall | New Partition_OG4 | 230 | 17.36 | LF | |
| Phase-2 | 09A-Drywall | New Acoustic Partition_OG4_Above Storefront & glass wall | 234 | 3.5 | LF | |
| Phase-2 | 09A-Drywall | New Furring wall_OF4 | 235 | 3.2 | LF | |
| Phase-2 | 09A-Drywall | Gypsum Partition_OG3P_H-4" _Corner Bead on top | 237 | 3.6 | LF | |
| Phase-2 | 09A-Drywall | New Partition_Above Storefront & glass wall_OG4 | 242 | 7.9 | LF | |
| Phase-2 | 09A-Drywall | New Acoustic Partition_OG4_Above Storefront & glass wall | 268 | 4.56 | LF | |
| Phase-2 | 09A-Drywall | New Partition_Above Storefront & glass wall_OG4 | 269 | 8.36 | LF | |

| | | | | | | |
|---------|-------------|--|-----|----|----|--|
| Phase-2 | 09A-Drywall | New Acoustic Partition_0G4_Above Storefront & glass wall | 271 | 14 | LF | |
| Phase-2 | 09A-Drywall | New Partition_0G4_Glass-Mat Water Resistant @ RR | 406 | 21 | LF | |

Note : *The quantities, numbers, scope, or any other information contained in this document has been compiled to the best of our knowledge. By utilizing or deriving any of the information contained in this document, you accept the information and quantities as accurate and waive any rights to any claims for errors in information. Precon Optimar does not warranty any of the information contained in this document. The information contained in this document are for informational purposes only and to be used as a guideline for quantities and pricing. It is the responsibility of the contractor performing the work to review quantities and finalize pricing and materials based on current prices.*



